

Ship? 09-14

Work Order ID 166165

166165

Page 1

Tuesday, September 12, 2017 10:46:05 AM

Item ID: D412-711-021 Accept *N900040100* Setup Start *NS1*
 Revision ID: Stop *NS2*
 Item Name: Vertical Reference Door Modification LH
 Start Date: 9/13/2017 Start Qty: 1.00 *1* Cust Item ID:
 Required Date: 9/15/2017 Req'd Qty: 1.00 *1* Customer:

Reference:

Approvals: Process Plan:  Date: SEP 12 2017 Tooling: Date: Run Start *NR1*
 QC: Date: SPC (Y/N): Date: Stop *NR2*

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr								
D412-711	L	SEP 13 2017 							
100	Document Control	0.00							
100	DOCUMENT CONTROL								
DC	Memo	0.00							
Doc.Control -USB or Paperwork	Photocopy bluefiles and create labels per PPP D412-711-021 CHG002								
120	Pick Kit	0.00							
120	Purchasing								
Packaging	Memo	0.00							
Packaging									
130	QC4- 100% Inspect kits for completeness	0.00							
130									
QC	Memo	0.03							
Quality Control									

DAS
28
9-89

SEP 13 2017

SEP 13 2017 DAS 6 9-89

DAS
28
9-89

SEP 13 2017

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval		
Description Work Order Deviation				Disposition				Completed By	
								Lead hand / Supervisor Approval Verification	
								QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY							
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐	No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐	Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐	Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐				
OTHER : ☐									

Work Order ID 166165

Tuesday, September 12, 2017 10:46:05 AM

166165

Page 2

Item ID: D412-711-021

Accept

N900040100

Setup Start

NS1

Revision ID:

Stop

NS2

Item Name: Vertical Reference Door Modification LH

Start Date: 9/13/2017 Start Qty: 1.00

1

Cust Item ID:

Required Date: 9/15/2017 Req'd Qty: 1.00

1

Customer:

Reference:

Approvals:

Process Plan: _____

Date: _____

Tooling: _____

Date: _____

Run Start

NR1

QC: _____

Date: _____

SPC (Y/N): _____

Date: _____

Stop

NR2Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run Hours

Tool ID

Tool #

Plan
CodeAccept
QtyReject
QtyReject
NumberInsp.
Stamp

150

Identify as per dwg & Stock Location: _____

0.00

150

Packaging

Memo

0.00

Packaging

Identify and pack for shipping as per PPP D412-711-021

Location: _____

PPP rev: _____

DAS
28
9-89

SEP 13 2017

160

QC21- Final Inspection - Work Order Release

0.00

160

QC

Memo

0.10

DAS
21
9-89

SEP 14 2017

Quality Control

DAS
21
9-89

SEP 14 2017

DQA: _____ Date: _____

WORK ORDER NON-CONFORMANCE / UPDATE



QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval		
Description Work Order Deviation				Disposition				Completed By	
85								Lead hand / Supervisor Approval Verification	
								QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY							
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐	No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐	Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐	Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐				
OTHER : ☐									

Tuesday, September 12, 2017 10:46:03 AM

166165

D412-711-021

Required Qty: 1.00

IPP Rev:B

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D4324-011		Manufactured	No			120	Each	1.0000	1	1			
D4324-011 Armrest Assembly DAS 28 9-89 SEP 14 2017 9-89 DAS 6 9-89													
				<u>Location</u>			<u>Loc Qty</u>		<u>Loc Code</u>				
				ST459			1						
				<u>160694</u>			1						
D412-761-043		Manufactured	No			120	Each	0.0000	1	1			
D412-761-043 Modified Latch Mechanism DAS 28 9-89 SEP 14 2017 9-89 DAS 6 9-89													
D412-711-101		Purchased	No			120	Each	5.0000	1	1			
D412-711-101 Replacement Vertical Reference Window DAS 28 9-89 SEP 14 2017 9-89 DAS 6 9-89													
				<u>Location</u>			<u>Loc Qty</u>		<u>Loc Code</u>				
				PKG			5						
				<u>164010</u>			5						
D3802-1-120		Manufactured	No			120	Each	1.0000	1	1			
D3802-1-120 Window Seal - 120" DAS 28 9-89 SEP 14 2017 9-89 DAS 6 9-89													
				<u>Location</u>			<u>Loc Qty</u>		<u>Loc Code</u>				
				ST639			1						
				<u>165240</u>			1						

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval		
Description Work Order Deviation				Disposition				Completed By	
								Lead hand / Supervisor Approval Verification	
								QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY							
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐	No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐	Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐	Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐				
OTHER : ☐									

Picklist Print

Tuesday, September 12, 2017 10:46:03 AM

Page 2

Work Order ID: 166165

166165

Parent Item: D412-711-021

D412-711-021

Parent Item Name: Vertical Reference Door Modification LH

Start Date: 9/13/2017

Required Date: 9/15/2017

Start Qty: 1.00

Required Qty: 1.00

D4165-1	Manufactured	No	120	Each	4.0000	1	1	DAS 6 9-89
D4165-1						**		
Doubler								
			<u>Location</u>	<u>Loc Qty</u>	<u>Loc Code</u>			
			ST236	4				
			161419	4				
D4165-3	Manufactured	No	120	Each	3.0000	1	1	DAS 6 9-89
D4165-3						**		
Inner Door Panel								
			<u>Location</u>	<u>Loc Qty</u>	<u>Loc Code</u>			
			ST235	3				
			161422	3				
D4165-5	Manufactured	No	120	Each	2.0000	1	1	DAS 6 9-89
D4165-5						**		
Aft Rib								
			<u>Location</u>	<u>Loc Qty</u>	<u>Loc Code</u>			
			ST236	2				
			161424	2				
D4165-7	Manufactured	No	120	Each	4.0000	1	1	DAS 6 9-89
D4165-7						**		
Fwd Rib								
			<u>Location</u>	<u>Loc Qty</u>	<u>Loc Code</u>			
			ST236	4				
			161417	4				
D4165-9	Manufactured	No	120	Each	2.0000	1	1	DAS 6 9-89
D4165-9						**		
Angle								
			<u>Location</u>	<u>Loc Qty</u>	<u>Loc Code</u>			
			ST237	2				
			161410	2				

Tuesday, September 12, 2017 10:46:04 AM

Shop Packet Print

Page 2

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS <table style="width:100%; border: none;"> <tr> <td style="border: none;">Skid-tube ☐</td> <td style="border: none;">Cross tube ☐</td> <td style="border: none;">Water Jet ☐</td> <td style="border: none;">Engineering ☐</td> </tr> <tr> <td style="border: none;">Machining ☐</td> <td style="border: none;">Small Fab ☐</td> <td style="border: none;">Prod. Eng. Coord. ☐</td> <td style="border: none;">Quality ☐</td> </tr> <tr> <td style="border: none;">Thermoforming ☐</td> <td style="border: none;">Finishing ☐</td> <td style="border: none;">Rec/Store/Packaging ☐</td> <td style="border: none;">Other ☐</td> </tr> <tr> <td style="border: none;">Large Fab ☐</td> <td style="border: none;">Composite ☐</td> <td style="border: none;">Supplier ☐</td> <td></td> </tr> </table>						Skid-tube ☐	Cross tube ☐	Water Jet ☐	Engineering ☐	Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐	Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐	Large Fab ☐	Composite ☐	Supplier ☐	
Skid-tube ☐	Cross tube ☐	Water Jet ☐	Engineering ☐																						
Machining ☐	Small Fab ☐	Prod. Eng. Coord. ☐	Quality ☐																						
Thermoforming ☐	Finishing ☐	Rec/Store/Packaging ☐	Other ☐																						
Large Fab ☐	Composite ☐	Supplier ☐																							
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval																		
Description Work Order Deviation				Disposition				Completed By																	
								Lead hand / Supervisor Approval Verification																	
								QC / QA Coordinator Approval																	
Root Cause		FAULT CATEGORY																							
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐	No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐	Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐	Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐			OTHER : ☐																	

Picklist Print

Tuesday, September 12, 2017 10:46:04 AM

Page 3

Work Order ID: 166165

166165

Parent Item: D412-711-021

D412-711-021

Parent Item Name: Vertical Reference Door Modification LH

Start Date: 9/13/2017

Required Date: 9/15/2017

Start Qty: 1.00

Required Qty: 1.00

D4165-11 Manufactured No

120 Each

3.0000

1 1

D4165-11

Door Cover Panel

**

DAS
28
9-89

Location

Loc Qty

Loc Code

ST235

3

161902

3

D4207-1

Manufactured No

120 Each

3.0000

1 1

D4207-1

Window Retainer

**

DAS
28
9-89

Location

Loc Qty

Loc Code

ST237

3

161967

3

D4207-3

Manufactured No

120 Each

3.0000

1 1

D4207-3

Instrument Window

**

DAS
28
9-89

Location

Loc Qty

Loc Code

ST237

3

163744

3

D4269-1

Manufactured No

120 Each

3.0000

1 1

D4269-1

Angle

**

DAS
28
9-89

Location

Loc Qty

Loc Code

ST084

3

160693

1

165232

2

SEP 14 2017

DAS
6
9-89

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval		
Description Work Order Deviation				Disposition				Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY							
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐				
Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐				
Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐				
Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐				
Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐				
Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐				
Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐				
Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐				
LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐				
Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐				
Past Expiry Date ☐	Manufacturing Process ☐								
Misidentified ☐	Past Due ☐								
		OTHER :							

Picklist Print

Tuesday, September 12, 2017 10:46:04 AM

Page 4

Work Order ID: 166165

166165

Parent Item: D412-711-021

D412-711-021

Parent Item Name: Vertical Reference Door Modification LH

Start Date: 9/13/2017

Required Date: 9/15/2017

Start Qty: 1.00

Required Qty: 1.00

D4269-3

Manufactured No

120

Each

3.0000

1

1

D4269-3

Angle

**

SEP 14 2017

DAS
6
9-89

Location

Loc Qty

Loc Code

ST084

3

160695

3

D4269-5

Manufactured No

120

Each

4.0000

1

1

D4269-5

Angle

**

Location

Loc Qty

Loc Code

ST237

4

160331

1

161889

3

D4269-7

Manufactured No

120

Each

3.0000

1

1

D4269-7

Angle

**

Location

Loc Qty

Loc Code

ST237

3

160332

1

161893

2

D4327-1

Manufactured No

120

Each

1.0000

1

1

D4327-1

Angle

**

Location

Loc Qty

Loc Code

ST237

1

163450

1

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date : _____		Step #: _____		QTY Effective : _____			MRB (QSI042) Approval		
Description Work Order Deviation				Disposition				Completed By _____ Lead hand / Supervisor Approval Verification : _____ QC / QA Coordinator Approval _____	
Root Cause		FAULT CATEGORY							
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐				
Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐				
Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐				
Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐				
Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐				
Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐				
Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐				
Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐				
LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐				
Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐				
Past Expiry Date ☐	Manufacturing Process ☐								
Misidentified ☐	Past Due ☐	OTHER : _____							

Picklist Print

Tuesday, September 12, 2017 10:46:04 AM

Page 5

Work Order ID: 166165

166165

Parent Item: D412-711-021

D412-711-021

Parent Item Name: Vertical Reference Door Modification LH

Start Date: 9/13/2017

Required Date: 9/15/2017

Start Qty: 1.00

Required Qty: 1.00

D4327-3 Manufactured No 120 Each 1.0000 1 1

D4327-3

Angle

DAS
28
9-89

Location

Loc Qty

Loc Code

ST237

1

163463

1

D4385-1

Manufactured No

120 Each

10.0000

2

2

D4385-1

Placard

DAS
28
9-89

Location

Loc Qty

Loc Code

ST088

10

156112

4

160140

6

2/3/2018

5/19/2018

AN3-3A

Purchased No

120 Each

108.0000

22

22

AN3-3A

Bolt

DAS
28
9-89

Location

Loc Qty

Loc Code

ST350

108

m137853

33

m138207

25

m138409

50

AN3-4A

Purchased No

120 Each

362.0000

20

20

AN3-4A

Bolt

DAS
28
9-89

Location

Loc Qty

Loc Code

over003

350

m138260

350

ST350

12

m137478

12

Tuesday, September 12, 2017 10:46:04 AM

Shop Packet Print

Page 5

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date : _____		Step #: _____		QTY Effective : _____			MRB (QSI042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval		
Description Work Order Deviation				Disposition					
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐		Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐					
OTHER : _____									

Picklist Print

Tuesday, September 12, 2017 10:46:04 AM

Page 6

Work Order ID: 166165

166165

Parent Item: D412-711-021

D412-711-021

Parent Item Name: Vertical Reference Door Modification LH

Start Date: 9/13/2017

Required Date: 9/15/2017

Start Qty: 1.00

Required Qty: 1.00

AN3-6A Purchased No 120 Each 96.0000 26 26

AN3-6A

Bolt

**

SEP 14 2017

DAS
6
9-89

DAS
28
9-89

Location

Loc Qty

Loc Code

ST350

96

m137412

96

AN3-12A Purchased No 120 Each 145.0000 1 1

AN3-12A

Bolt

**

SEP 14 2017

DAS
6
9-89

DAS
28
9-89

Location

Loc Qty

Loc Code

ST349

145

153854

145

NAS1149F0332P Purchased No 120 Each 1,409.000 92 92

NAS1149F0332P

Washer

**

SEP 14 2017

DAS
6
9-89

DAS
28
9-89

Location

Loc Qty

Loc Code

GA

125

m133709

125

ST262

1284

m138209

1284

CR3242-4-2 Purchased No 120 Each 84.0000 34 34

CR3242-4-2

RIVET

**

SEP 13 2017

DAS
6
9-89

DAS
28
9-89

Location

Loc Qty

Loc Code

ST318

84

m137061

1

m137597

83

Tuesday, September 12, 2017 10:46:04 AM

Shop Packet Print

Page 6

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval		
Description Work Order Deviation				Disposition				Completed By _____ Lead hand / Supervisor Approval Verification _____ QC / QA Coordinator Approval _____	
Root Cause		FAULT CATEGORY							
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐				
Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐				
Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐				
Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐				
Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐				
Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐				
Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐				
Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐				
LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐				
Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐				
Past Expiry Date ☐	Manufacturing Process ☐								
Misidentified ☐	Past Due ☐	OTHER : _____							

Picklist Print

Page 7

Tuesday, September 12, 2017 10:46:04 AM

Work Order ID: 166165

166165

Parent Item: D412-711-021

D412-711-021

Parent Item Name: Vertical Reference Door Modification LH

Start Date: 9/13/2017

Required Date: 9/15/2017

Start Qty: 1.00

Required Qty: 1.00

MS20426AD3-3

Purchased

No

120

Each

1,790.000

135

135

MS20426AD3-3

RIVET

**

SEP 13 2017

DAS
6
9-89

Location

Loc Qty

Loc Code

FG107/108

360

M137350

80

M138217

280

fg108

200

M134946

200

ST312

1230

M135274

1230

135

MS20426AD4-3

Purchased

No

120

Each

3,520.000

140

140

MS20426AD4-3

Rivet

**

SEP 13 2017

DAS
6
9-89

Location

Loc Qty

Loc Code

GA

211

113064

211

ST312

3309

m137597

3309

134370

MS20470AD3-3

Purchased

No

120

Each

5,864.000

25

25

MS20470AD3-3

RIVET, UNIVERSAL HEAD

**

SEP 13 2017

DAS
6
9-89

Location

Loc Qty

Loc Code

GA

719

1065

719

ST310

5145

16941

5145

25

Tuesday, September 12, 2017 10:46:04 AM

Shop Packet Print

Page 7

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval Completed By _____ Lead hand / Supervisor Approval Verification _____ QC / QA Coordinator Approval _____		
Description Work Order Deviation				Disposition					
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐		OTHER : _____					

Picklist Print

Tuesday, September 12, 2017 10:46:04 AM

Page 8

Work Order ID: 166165

166165

Parent Item: D412-711-021

D412-711-021

Parent Item Name: Vertical Reference Door Modification LH

Start Date: 9/13/2017

Required Date: 9/15/2017

Start Qty: 1.00

Required Qty: 1.00

MS20470AD4-3

Purchased

No

120

Each

1,342.000

90

90

MS20470AD4-3

Rivet, Universal Head

**

DAS
6
9-89

SEP 13 2017

DAS
28
9-89

Location

Loc Qty

Loc Code

GA

779

2193

87

m135536

692

ST310

563

m135536

563

MS21042L3

Purchased

No

120

Each

1,615.000

24

24

MS21042L3

Nut

**

DAS
6
9-89

SEP 13 2017

DAS
28
9-89

Location

Loc Qty

Loc Code

FP001

58

m135945

58

GA

332

m134360

102

M136665

230

OVER007

500

m138408

500

ST303

725

m138230

500

m138326

225

24

Tuesday, September 12, 2017 10:46:04 AM

Shop Packet Print

Page 8

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date : _____		Step # : _____		QTY Effective : _____			MRB (QSI042) Approval Completed By _____ Lead hand / Supervisor Approval Verification _____ QC / QA Coordinator Approval _____		
Description Work Order Deviation				Disposition					

Root Cause			FAULT CATEGORY							
Environment ☐	☐	No Re-verification	☐	Pressure/Forced	☐	Temperature/Cure	☐	Power Loss/Surge	☐	Positioned Wrong
Design ☐	☐	Operator	☐	Bending	☐	Set-up	☐	Folio/Program	☐	Outside Dimensions
Doc/Data ☐	☐	Offset/Setup	☐	Centre Not Concentric	☐	BOM/Route	☐	Grain	☐	Over/Under tolerance
Equip/Tooling ☐	☐	Supplier	☐	Cracks	☐	Broken/Damage/Defect	☐	Weld	☐	Part Incorrect
Handling/Pre ☐	☐	Training	☐	Crimp/Kink/Ripple/Wave	☐	Inspection Incomplete/Unqualified	☐	Wrong Stock Pulled	☐	Part Lost/Missing
Material ☐	☐	Use for Testing	☐	Cuffs	☐	Contamination	☐	Out of Sequence	☐	Part Moved
Internal Transport ☐	☐	Poor Information	☐	Crushing	☐	Countersink	☐	Off-set	☐	Drawing
Tribal Knowledge ☐	☐	Rushing	☐	Heat Treat	☐	Cut Too Short	☐	Mislabeled	☐	Finish
LOA ☐	☐	Product Improvement	☐	Wave/Twist in Tube	☐	Instructions Incomplete/Unclear	☐	Fit/Function	☐	Misread
Substation ☐	☐	Process Improvement	☐	Marks/Chatter	☐	Drill Holes	☐	Misaligned/off center	☐	Turning Sequence
Past Expiry Date ☐	☐	Manufacturing Process	OTHER : _____							
Misidentified ☐	☐	Past Due								

Picklist Print

Tuesday, September 12, 2017 10:46:04 AM

Page 9

Work Order ID: 166165

166165

Parent Item: D412-711-021

D412-711-021

Parent Item Name: Vertical Reference Door Modification LH

Start Date: 9/13/2017

Required Date: 9/15/2017

Start Qty: 1.00

Required Qty: 1.00

MS21059L3

Purchased

No

120

Each

105.0000

4

4

MS21059L3

Nut Plate

**

DAS
6
9-89

SEP 13 2017

DAS
28
9-89

Location

Loc Qty

Loc Code

GA

47

M137412

1

M137659

30

M137710

16

ST301

58

M138040

58

MS21069L3

Purchased

No

120

Each

123.0000

34

34

MS21069L3

ANCHOR NUT

**

DAS
6
9-89

SEP 13 2017

DAS
28
9-89

Location

Loc Qty

Loc Code

ST299

123

m137459

23

m137820

100

MS21069L08

Purchased

No

120

Each

402.0000

8

8

MS21069L08

ANCHOR NUT

**

DAS
6
9-89

SEP 13 2017

DAS
28
9-89

Location

Loc Qty

Loc Code

ST299

402

123522

402

MS21071L3

Purchased

No

120

Each

53.0000

3

3

MS21071L3

ANCHOR NUT

**

DAS
6
9-89

SEP 13 2017

DAS
28
9-89

Location

Loc Qty

Loc Code

S299

50

m137680

50

ST299

3

125654

3

Tuesday, September 12, 2017 10:46:04 AM

Shop Packet Print

Page 9

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval		
Description Work Order Deviation				Disposition				Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY							
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐				
Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐				
Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐				
Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐				
Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐				
Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐				
Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐				
Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐				
LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐				
Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐				
Past Expiry Date ☐	Manufacturing Process ☐								
Misidentified ☐	Past Due ☐	OTHER :							

Picklist Print

Page 10

Tuesday, September 12, 2017 10:46:04 AM

Work Order ID: 166165

166165

Parent Item: D412-711-021

D412-711-021

Parent Item Name: Vertical Reference Door Modification LH

Start Date: 9/13/2017

Required Date: 9/15/2017

Start Qty: 1.00

Required Qty: 1.00

MS21071L08

Purchased

No

120

Each

145.0000

1

1

MS21071L08

ANCHOR NUT

**

DAS

6

9-89

SEP 13 2017

DAS
28
9-89

Location

Loc Qty

Loc Code

ST299

145

102587

45

103447

100

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date : _____		Step # : _____		QTY Effective : _____			MRB (QSI042) Approval		
Description Work Order Deviation				Disposition				Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY							
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐				
Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐				
Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐				
Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐				
Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐				
Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐				
Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐				
Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐				
LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐				
Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐				
Past Expiry Date ☐	Manufacturing Process ☐								
Misidentified ☐	Past Due ☐	OTHER : _____							

QTY -011	QTY -013	QTY -015	QTY -017	QTY -019	QTY -021	QTY -041	QTY -043	PART NUMBER	DESCRIPTION
X								D412-711-011	VERTICAL REFERENCE DOOR INSTALLATION, 212/412
	X							D205-711-013	VERTICAL REFERENCE DOOR INSTALLATION, 205/210
		X						D204-711-015	VERTICAL REFERENCE DOOR INSTALLATION, 204
			X					D214-711-017	VERTICAL REFERENCE DOOR INSTALLATION, 214
				X				D212-711-019	VERTICAL REFERENCE DOOR EAGLE SINGLE
					X			D412-711-021	VERTICAL REFERENCE DOOR KIT
^1	^1	^1	^1	^1		X		D412-711-041	VERTICAL REFERENCE DOOR ASSEMBLY
							X	D412-711-043	SNAP VENT KIT
					1	1		D412-761-043	MODIFIED LATCH MECHANISM KIT, LH (REPLACES EA20469-23/-24/-25)
					1	1		D412-711-101	REPLACEMENT WINDOW (REPLACES EAGLE P/N EB212-100L / EA20469-3)
					1	1		D3802-1-120	RUBBER STRIP
							2	D3932-1	SNAP VENT
					1	1		D4165-1	DOUBLER
					1	1		D4165-3	DOOR INNER SKIN (REPLACES EA20469-18)
					1	1		* D4165-5	AFT RIB (REPLACES EA20469-34)
					1	1		** D4165-7	FWD RIB (REPLACES EA20469-31)
					1	1		D4165-9	ANGLE (REPLACES EA20469-17)
					1	1		D4165-11	DOOR COVER PANEL (REPLACES EA20469-21)
					1	1		D4207-1	WINDOW RETAINER (REPLACES EA20469 -14)
					1	1		D4207-3	WINDOW (REPLACES EA20469-13)
					1	1		* D4269-1	ANGLE (REPLACES EA20469-33)
					1	1		** D4269-3	ANGLE (REPLACES EA20469-30)
					1	1		** D4269-5	ANGLE (REPLACES EA20469-29)
					1	1		* D4269-7	ANGLE (REPLACES EA20469-32)
					1	1		D4324-011	ARM REST ASSEMBLY (REPLACES EA20469-16)
					1	1		D4327-1	ANGLE (REPLACES EA20469-11)
					1	1		D4327-3	ANGLE (REPLACES EA20469-07)
					2	2		D4385-1	PLACARD

* PART OF EA20469-10 REAR RIB ASSEMBLY
 ** PART OF EA20469-12 FWD RIB ASSEMBLY

APPROVED

DESIGN	RF	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWN	MB		
CHECKED	ML	DRAWING NO.	REV. L
MFG. APPR.	N/A	D412-711	SHEET 2 OF 6
APPROVED	HS	TITLE	SCALE
DE APPR.	DS	VERTICAL REFERENCE DOOR NTS	
DATE	17.01.20	COPYRIGHT © 2004 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	

QTY -011	QTY -013	QTY -015	QTY -017	QTY -019	QTY -021	QTY -041	PART NUMBER	DESCRIPTION
					22	22	AN3-3A	BOLT
					20	20	AN3-4A	BOLT
					26	26	AN3-6A	BOLT
					1	1	AN3-12A	BOLT
					92	92	NAS1149F0332P	WASHER (OR AN960-10L)
					34	34	CR3242-4-2	RIVET
					135	135	MS20426AD3-3	RIVET
					140	140	MS20426AD4-3	RIVET
					25	25	MS20470AD3-3	RIVET
					90	90	MS20470AD4-3	RIVET
					24	24	MS21042L3	NUT
					4	4	MS21059L3	NUT PLATE
					34	34	MS21069L3	NUT PLATE
					8	8	MS21069L08	NUT PLATE
					3	3	MS21071L3	NUT PLATE
					1	1	MS21071L08	NUT PLATE
						1	204-030-853-125	LH COPILOT DOOR (204-030-853-137/-155)
1							D412-711-111	WIRING HARNESS, 212/412
^B 1							^B D4268-043	INSTRUMENT PANEL, 212/412 (REPLACES EA20469-15-412)
	1						D205-711-113	WIRING HARNESS, 205
	^B 1						^B D4268-041	INSTRUMENT PANEL, 205 (REPLACES EA20469-15-205)
		1					D204-711-115	WIRING HARNESS, 204
		^B 1					^B EA20469-15-204	INSTRUMENT PANEL, 204
			1				D214-711-117	WIRING HARNESS, 214
			^B 1				^B EA20469-15-214	INSTRUMENT PANEL, 214
				1			D212-711-119	WIRING HARNESS, EAGLE SINGLE
				^B 1			^B D4268-047	INSTRUMENT PANEL, EAGLE SINGLE

- (A) IF CUSTOMER PREFERS TO SUPPLY AND MODIFY THEIR OWN DOOR, D412-711-021 SHOULD BE SUPPLIED IN LIEU OF D412-711-041
(B) INSTRUMENT PANEL INCLUDED WITH HARNESS ABOVE

NOTES

1) WIRING HARNESSES:

For Bell 204/205/210 Wiring Harnesses, use drawing D2046904.

For Bell 212 Wiring Harnesses, use drawing D2046903*.

For Bell 214 Wiring Harnesses, use drawing D214-761-511.

For Bell 412 Wiring Harnesses, use drawing D412-711-901.

For Bell 212 modified per SH07-28/SR02831NY use D212-761-224 or D212-761-225 depending on aircraft s/n.

* Despite the note on the drawing, D2046903 is applicable to all 212 aircraft serial numbers

Wiring Harnesses will vary depending on aircraft s/n.

2) D412-711-101 REPLACEMENT WINDOW:

To increase downward viewing clarity, it is acceptable to cut a small section from the replacement window on its downward side per Figure 1 of this document. The cutout can be a maximum of 9.00" wide x 17.00" long (229mm x 432mm), measured along the profile of the replacement window. The corners of the cutout must have a minimum radius of 2" (50mm). The cutout should be located at least 1.0" (25mm) from the flange. The actual shape of the cutout can vary as desired, as long as the overall dimensions are within the specified limits. See Figure 1 for reference.

3) D412-711-043 SNAP VENT KIT:

It is acceptable to install a total of up to 2X D3932-1 Snap Vents (available from Dart) onto the D412-711-101 Replacement Window to provide ventilation into the cabin. Refer to Figure 1 for acceptable locations and size of cutouts.

4) It is acceptable to use MS21042L3 nuts to install the window in lieu of anchor nuts shown on D2046901.

APPROVED

DESIGN	RF	DART AEROSPACE LTD	
DRAWN	MB	HAWKESBURY, ONTARIO, CANADA	
CHECKED	ML	DRAWING NO.	REV. L
MFG. APPR.	N/A	D412-711	SHEET 3 OF 6
APPROVED	HS	TITLE	SCALE
DE APPR.	DS	VERTICAL REFERENCE DOOR NTS	
DATE	17.01.20	COPYRIGHT © 2004 BY DART AEROSPACE LTD	
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.			